

**REQUEST FOR PROPOSALS # 050501**  
**SUPPLEMENTAL INFORMATION – NOTICE #2**

**May 24, 2024**

This notice is intended to provide supplemental information to all prospective respondents regarding the Asbestos and Environmental Hygienist Survey of RFP #050501. This notice focuses on changes made to the total number of units to be included in this project. In summary, the revised Attachment I and II which is attached hereto and made a part hereof, supersedes all other notices and information previously provided regarding the number of units to be assessed.

The final categorical breakdown is as follows:

**Assessment Required**

Total Vacant Units 71            Asbestos 71            Lead Base Paint 37    Mold/Mildew: 53

**Any further questions regarding the RFP or this Supplemental Notice should be directed to:**

Felipe Barsky  
Project Manager  
Nelson and Associates.  
1204 N.W. Ave L Terrace  
Belle Glade, FL. 33430  
Office 561-996-7366  
Fax 561-996-9503  
Email: felipe.barsky@nelsonasc.com

Okeechobee- Vacant Units "Attachment I"

#			ADDRESS	Unit Size	Building Type	YR. BUILT	Lead Base Paint	Asbestos
1	V		2A BETHUNE ST	Efficiency	Quad	1968	X	X*
2	V		57 BETHUNE ST	3 BR	Single	1968	X	X*
3	V		29 CARVER ST	4 BR	Single	1968	X	X
4	V		12 DAVIS COURT	3 BR	Single	1968	X	X
5	V		24 DAVIS ST	3 BR	Single	1968	X	X*
6	V		26 DAVIS ST	3 BR	Single	1968	X	X*
7	V	ADA	72 DAVIS ST	3 BR	Single	1982		X*
8	V	ADA	89A DAVIS ST	2 BR	Duplex	1982		X*
9	V		39 DAVIS TERR	3 BR	Single	1968	X	X*
10	V	ADA	60 EVERGLADES TERR	3 BR	Single	1982		X*
11	V	ADA	67 EVERGLADES TERR	3 BR	Single	1982		X*
12	V	ADA	22B ROOSEVELT ST	2 BR	Duplex	1982		X*
13	V	ADA	54 DAVIS ST	3 BR	Single	1982		X

X\*: Roofs on these buildings will be replaced. Roofs must be checked for asbestos

Osceola - Vacant Units "Attachment I"

#			ADDRESS	Unit Size	Building Type	YR. BUILT	Lead Base Paint	Asbestos
1	V	ADA	1524 NW 12TH DRIVE	Efficiency	Quad	1968	X	X*
2	V	ADA	1630 NW 12TH DRIVE	1 BR	Duplex	1968	X	X*
3	V		1251 NW 11TH ST	3 BR	Single	1968	X	X*
4	V		1633 NW 12TH ST	2 BR	Duplex	1982		X*
5	V		1628 NW 12TH ST	3 BR	Single	1982		X*

X\*: Roofs on these buildings will be replaced. Roofs must be checked for asbestos

### Okeechobee- Vacant Units "Attachment II"

#			ADDRESS	Unit Size	Building Type	YR. BUILT	Lead Base Paint	Asbestos	Mold
1	UH		26A BETHUNE PLACE	2 BR	Duplex	1982		X	X
2	UH	ADA	5A BETHUNE ST	Efficiency	Quad	1968	X	X*	X
3	UH	ADA	9C BETHUNE ST	Efficiency	Quad	1968	X	X	X
4	UH	ADA	11B BETHUNE ST	Efficiency	Sixplex	1968	X	X	X
5	UH	ADA	11D BETHUNE ST	Efficiency	Sixplex	1968	X	X	X
6	UH		46B BETHUNE TERR	2 BR	Duplex	1982		X	X
7	UH		48A BETHUNE TERR	2 BR	Duplex	1988		X*	X
8	UH		23 CARVER ST	4 BR	Single	1968	X	X*	X
9	UH		37 CARVER ST	3 BR	Single	1968	X	X*	X
10	UH		17 DAVIS DRIVE	3 BR	Single	1968	X	X*	X
11	UH		19 DAVIS DRIVE	3 BR	Single	1968	X	X*	X
12	UH		2 DAVIS ST	3 BR	Single	1968	X	X*	X
13	UH		10 DAVIS ST	3 BR	Single	1968	X	X*	X
14	UH	ADA	48 DAVIS ST	3 BR	Single	1982		X*	X
15	UH	ADA	53A DAVIS ST	2 BR	Duplex	1982		X*	X
16	UH	ADA	64A DAVIS ST	2 BR	Duplex	1982		X*	X
17	UH		18 EVERGLADES ST	4 BR	Single	1968	X	X*	X
18	UH		22 EVERGLADES ST	3 BR	Single	1968	X	X*	X
19	UH		24B EVERGLADES ST	2 BR	Duplex	1982		X*	X
20	UH		25B EVERGLADES ST	2 BR	Duplex	1988		X	X
21	UH	ADA	59 EVERGLADES TERR	4 BR	Single	1982		X*	X
22	UH	ADA	65 EVERGLADES TERR	3 BR	Single	1982		X	X
23	UH		7 ROOSEVELT ST	3 BR	Single	1968	X	X*	X
24	UH		12 ROOSEVELT ST	3 BR	Single	1968	X	X*	X
25	UH		13 ROOSEVELT ST	3 BR	Single	1968	X	X*	X
26	UH		15 ROOSEVELT ST	4 BR	Single	1968	X	X*	X
27	UH		16 ROOSEVELT ST	3 BR	Single	1968	X	X*	X
28	UH		18 ROOSEVELT ST	3 BR	Single	1968	X	X*	X
29	UH		29 ROOSEVELT ST	3 BR	Single	1982		X	X
30	UH	ADA	31B ROOSEVELT ST	2 BR	Duplex	1982		X	X
31	UH		53 ROOSEVELT ST	3 BR	Single	1968	X	X	X
32	UH		66 ROOSEVELT ST	3 BR	Single	1968	X	X*	X
33	UH		74 ROOSEVELT ST	3 BR	Single	1968	X	X*	X
34	UH		62A BETHUNE TERR	2 BR	Duplex	1990		X	X
35	UH		26B ROOSEVELT PL	2 BR	Duplex	1990		X*	X

**X\*:** Roofs on these buildings will be replaced. Roofs must be checked for asbestos

### Osceola- Vacant Units "Attachment II"

#			ADDRESS	Unit Size	Building Type	YR. BUILT	Lead Base Paint	Asbestos	Mold
1	UH	ADA	1378 NW 12TH DRIVE	1 BR	Quad	1997		X*	X
2	UH		1410 NW 12TH DRIVE	Efficiency	Sixplex	1968	X	X*	X
3	UH		1444 NW 12TH DRIVE	Efficiency	Quad	1968	X	X	X
4	UH	ADA	1494 NW 12TH ST	1 BR	Duplex	1968	X	X*	X
5	UH		1603 NW 12TH ST	2 BR	Duplex	1982		X*	X
6	UH		1608 NW 11TH ST	2 BR	Duplex	1982		X*	X
7	UH		1619 NW 11TH ST	2 BR	Duplex	1982		X*	X
8	UH	ADA	1623 NW 11TH ST	2 BR	Duplex	1982		X*	X
9	UH	ADA	1625 NW 11TH ST	2 BR	Duplex	1982		X*	X
10	UH		1153 NW P PL	2 BR	Duplex	1990		X	X
11	UH		1674 NW 12TH ST	2 BR	Duplex	1988		X*	X
12	UH		1200 N.W. P TERRACE	2 BR	Duplex	1988		X*	X
13	UH		1471 NW 12TH ST	3 BR	Single	1968	X	X	X
14	UH		1411 NW 12TH ST	3 BR	Single	1968	X	X*	X
15	UH		1351 NW 12TH ST	3 BR	Single	1968	X	X	X
16	UH		1638 NW 12TH ST	2 BR	Duplex	1982		X	X
17	UH		1491 NW 11TH ST	2 BR	Duplex	1990		X*	X
18	UH		1332 NW 11TH ST	2 BR	Duplex	1990		X*	X

X\*:                      Roofs on these buildings will be replaced. Roofs must be checked for asbestos